

PHOENIX

Telescopic lifting column

Design features

Functions

- Absorbing high compressive and tensile forces up to 25 kN
- Integrated linear guide
- Closed and low-maintenance design
- Eccentric load application permitted
- Self-locking on standstill (with single-stage trapezoidal thread)*
- Duty cycle of 20%/h or 15%/10 min

Basic equipment

- Short safety nut (for trapezoidal and AGS threads)
- End position limit
 - Inductive limit switches (single-stage lifting columns)
 - Gear limit switches (multi-stage lifting columns)

Options

- Shaft encoder
- Special head or foot plate
- Direct attachment of IEC motors
- Ball screws (single-stage columns)
- Multi-start screws
- Specific models also in special design with a safety nut that can be deactivated electrically
- Special customer wishes




*Vibrations, sliding conditions can influence self-locking.
We also recommend use of a brake motor.

PHOENIX

Mounting positions and schematic diagrams


Mounting positions




Schematic diagram

Lifting column, mechanically synchronized


Schematic view 1.1




Schematic view 3.1




Schematic view 3.2





Schematic view 2.1



Schematic view 2.2



Schematic view 4.1



PHOENIX

Selection table

Selection table PHOENIX						
Series	PH34 M1	Single-stage			Multi-stage	
		PH45 M2	PH56 M3	PH56 G15	PH46 M3	PH 36 M3
Gearbox type	M	M	M	G	M	M
Number of levels	single-stage	single-stage	single-stage	single-stage	two-stage	three-stage
F _{dyn}	[kN]	5	10	25	15	10
F _{stat}	[kN]	5	10	25	15	25
Standard screw	T24x5	T30x6	T36x6	T30x6	A30x32	A30x32
Ball screw (Ku)	K20x20	K25x25	K40x40	K32x20	-	-
Ratio N	4	4	6	2	6	6
Ratio L	16	16	24	3	24	24
Max. power 20 % at ambient temperature 20 °C	[kW]	0.2	0.3	0.5	1	0.5
Max. power 10 % at ambient temperature 20 °C	[kW]	0.42	0.6	1.1	1.3	1.1
Overall efficiency N	0.29	0.28	0.24	See diagram efficiency, page 41	0.43	0.38
Overall efficiency L	0.22	0.2	0.17		0.3	0.27
Max. torque on the input shaft	[Nm]	3.4	7.1	18	50/19*	18
Max. speed	[1/min]	1500	1500	1500	3000	1500
Weight empty	[kg]	14	18	26	30	31
Weight per 100 mm stroke	[kg]	2.6	3.4	4	3.6	3
* Ratio N/L						

Gearbox

M: Worm gear

High ratio possible

Low noise

High load capacity

Economical

G: Bevel gear

Permanently resilient

Multiple drives can be implemented

Good efficiency

Low wear

Nearly unchanged twist play

Screw types

T: Trapezoidal screw (Tr)

Self-locking*

Economical

K: Ball screw (Ku)

High efficiency

A: AGS screw (AGS)

Special thread for use in multi-stage screw jacks
element



Tr screw



Ball screw (Ku)





AGS screw

PHOENIX

Flow chart

Flow chart



Please contact Columbus McKinnon
Engineered Products GmbH:
Phone: +49 (0) 8233 2121-777
E-mail: sales.kissing@cmco.eu

PHOENIX

Performance tables SINGLE-STAGE – trapezoidal screw

Performance table PHOENIX PH34 M1, Tr 24x5

Speed n	Lifting speed		5 kN		4 kN		3 kN		2.5 kN		2 kN		1.5 kN		1 kN	
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L
	[1/min]	[m/min]	4 Nm	1 Nm	3 Nm	1 Nm	2 Nm	1 Nm	2 Nm	1 Nm	2 Nm	1 Nm	1 Nm	1 Nm	1 Nm	0 Nm
1500	1.88	0.47	0.6	0.2	0.5	0.2	0.4	0.1	0.3	0.1	0.3	0.1	0.2	0.1	0.2	0.1
1000	1.25	0.31	0.4	0.1	0.3	0.1	0.3	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1
750	0.94	0.23	0.3	0.1	0.2	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1
600	0.75	0.19	0.2	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
500	0.63	0.16	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
300	0.38	0.09	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
100	0.13	0.03	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
50	0.06	0.02	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1

Performance table PHOENIX PH45 M2, Tr 30x6

Speed n	Lifting speed		10 kN		8 kN		6 kN		4 kN		3 kN		2 kN		1 kN	
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L
	[1/min]	[m/min]	9 Nm	3 Nm	7 Nm	3 Nm	6 Nm	2 Nm	4 Nm	1 Nm	3 Nm	1 Nm	2 Nm	1 Nm	1 Nm	1 Nm
1500	2.25	0.56	1.4	0.5	1.1	0.4	0.9	0.3	0.6	0.2	0.5	0.2	0.3	0.1	0.2	0.1
1000	1.5	0.38	0.9	0.3	0.8	0.3	0.6	0.2	0.4	0.1	0.3	0.1	0.2	0.1	0.1	0.1
750	1.13	0.28	0.7	0.2	0.6	0.2	0.4	0.1	0.3	0.1	0.2	0.1	0.2	0.1	0.1	0.1
600	0.9	0.23	0.6	0.2	0.5	0.2	0.3	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1
500	0.75	0.19	0.5	0.2	0.4	0.1	0.3	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1
300	0.45	0.11	0.3	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
100	0.15	0.04	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
50	0.08	0.02	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1

Performance table PHOENIX PH56 M3, Tr 36x6

Speed n	Lifting speed		25 kN		20 kN		15 kN		10 kN		5 kN		2.5 kN		1 kN	
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L
	[1/min]	[m/min]	17 Nm	6 Nm	13 Nm	5 Nm	10 Nm	4 Nm	7 Nm	3 Nm	4 Nm	1 Nm	2 Nm	1 Nm	1 Nm	0 Nm
1500	1.5	0.38	2.6	0.9	2.1	0.8	1.6	0.6	1.1	0.4	0.6	0.2	0.3	0.1	0.2	0.1
1000	1	0.25	1.7	0.6	1.4	0.5	1.1	0.4	0.7	0.3	0.4	0.1	0.2	0.1	0.1	0.1
750	0.75	0.19	1.3	0.5	1.1	0.4	0.8	0.3	0.5	0.2	0.3	0.1	0.2	0.1	0.1	0.1
600	0.6	0.15	1	0.4	0.8	0.3	0.6	0.2	0.4	0.2	0.2	0.1	0.1	0.1	0.1	0.1
500	0.5	0.13	0.9	0.3	0.7	0.3	0.5	0.2	0.4	0.1	0.2	0.1	0.1	0.1	0.1	0.1
300	0.3	0.08	0.5	0.2	0.4	0.2	0.3	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1
100	0.1	0.03	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
50	0.05	0.01	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1

Performance table PHOENIX PH56 G15, Tr 30x6

Speed n	Lifting speed		15 kN		12.5 kN		10 kN		7.5 kN		5 kN		2.5 kN		1 kN	
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L
	[1/min]	[m/min]	20 Nm	13 Nm	16 Nm	11 Nm	13 Nm	9 Nm	10 Nm	7 Nm	7 Nm	5 Nm	4 Nm	4 Nm	3 Nm	2 Nm
3000	9	6	6.6	4.6	5.6	3.9	4.6	3.2	3.6	2.6	2.6	1.9	1.7	1.3	1.1	0.9
2250	6.75	4.5	5	3.4	4.2	2.9	3.5	2.4	2.7	1.9	2	1.4	1.2	0.9	0.8	0.7
1500	4.5	3	3.3	2.3	2.8	1.9	2.3	1.6	1.8	1.3	1.3	1	0.8	0.6	0.5	0.4
1000	3	2	2.2	1.5	1.9	1.3	1.5	1.1	1.2	0.9	0.9	0.6	0.6	0.4	0.4	0.3
750	2.25	1.5	1.7	1.1	1.4	1	1.2	0.8	0.9	0.6	0.7	0.5	0.4	0.3	0.3	0.2
500	1.5	1	1.1	0.8	0.9	0.6	0.8	0.5	0.6	0.4	0.4	0.3	0.3	0.2	0.2	0.1
300	0.9	0.6	0.7	0.5	0.6	0.4	0.5	0.3	0.4	0.3	0.3	0.2	0.2	0.1	0.1	0.1
100	0.3	0.2	0.2	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1

Max. duty cycle at 20 °C ambient temperature: Operating mode S3 20% – 60 min. Operating mode S3 10% – 60 min. static only (dynamic not allowed)

PHOENIX

Performance tables MULTI-STAGE – AGS screw

Performance table PHOENIX PH46 M3, AGS32

Speed n	Lifting speed		10 kN		8 kN		6 kN		4 kN		3 kN		2 kN		1 kN	
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L
			21 Nm	8 Nm	17 Nm	6 Nm	13 Nm	5 Nm	9 Nm	3 Nm	7 Nm	3 Nm	5 Nm	2 Nm	3 Nm	1 Nm
[1/min]	[m/min]		P [kW]													
1500	8	2	3.3	1.2	2.6	0.9	2	0.7	1.4	0.5	1.1	0.4	0.8	0.3	0.5	0.2
1000	5.33	1.33	2.2	0.8	1.8	0.6	1.3	0.5	0.9	0.3	0.7	0.3	0.5	0.2	0.3	0.1
750	4	1	1.6	0.6	1.3	0.5	1	0.4	0.7	0.3	0.5	0.2	0.4	0.1	0.2	0.1
600	3.2	0.8	1.3	0.5	1.1	0.4	0.8	0.3	0.6	0.2	0.4	0.2	0.3	0.1	0.2	0.1
500	2.67	0.67	1.1	0.4	0.9	0.3	0.7	0.2	0.5	0.2	0.4	0.1	0.3	0.1	0.2	0.1
300	1.6	0.4	0.7	0.2	0.5	0.2	0.4	0.1	0.3	0.1	0.2	0.1	0.2	0.1	0.1	0.1
100	0.53	0.13	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
50	0.27	0.07	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1

Performance table PHOENIX PH36 M3, AGS32

Speed n	Lifting speed		8 kN		7 kN		6 kN		5 kN		4 kN		2 kN		1 kN	
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L
			19 Nm	7 Nm	17 Nm	6 Nm	15 Nm	5 Nm	12 Nm	4 Nm	10 Nm	4 Nm	6 Nm	2 Nm	3 Nm	1 Nm
[1/min]	[m/min]		P [kW]													
1500	8	2	3	1.1	2.6	0.9	2.3	0.8	1.9	0.7	1.6	0.6	0.9	0.3	0.5	0.2
1000	5.33	1.33	2	0.7	1.7	0.6	1.5	0.5	1.3	0.5	1	0.4	0.6	0.2	0.3	0.1
750	4	1	1.5	0.5	1.3	0.5	1.1	0.4	1	0.3	0.8	0.3	0.4	0.2	0.3	0.1
600	3.2	0.8	1.2	0.4	1	0.4	0.9	0.3	0.8	0.3	0.6	0.2	0.3	0.1	0.2	0.1
500	2.67	0.67	1	0.4	0.9	0.3	0.8	0.3	0.6	0.2	0.5	0.2	0.3	0.1	0.2	0.1
300	1.6	0.4	0.6	0.2	0.5	0.2	0.5	0.2	0.4	0.1	0.3	0.1	0.2	0.1	0.1	0.1
100	0.53	0.13	0.2	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
50	0.27	0.07	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1

Max. duty cycle at 20 °C ambient temperature: Operating mode S3 20% – 60 min. Operating mode S3 10% – 60 min. static only (dynamic not allowed)

PHOENIX

Performance tables SINGLE-STAGE – ball screw (Ku)


Performance table PHOENIX PH34 M1, Ku20x20																	
Speed n	Lifting speed		5 kN		4 kN		3 kN		2.5 kN		2 kN		1.5 kN		1 kN		
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L	
[1/min]	[m/min]		7 Nm	2 Nm	6 Nm	2 Nm	5 Nm	2 Nm	4 Nm	1 Nm	3 Nm	1 Nm	3 Nm	1 Nm	2 Nm	1 Nm	
P [kW]																	
1500	7.5	1.88	1.1	0.4	0.9	0.3	0.7	0.2	0.6	0.2	0.5	0.2	0.4	0.1	0.3	0.1	
1000	5	1.25	0.8	0.2	0.6	0.2	0.5	0.2	0.4	0.1	0.3	0.1	0.3	0.1	0.2	0.1	
750	3.75	0.94	0.6	0.2	0.5	0.2	0.4	0.1	0.3	0.1	0.3	0.1	0.2	0.1	0.2	0.1	
600	3	0.75	0.5	0.1	0.4	0.1	0.3	0.1	0.2	0.1	0.2	0.1	0.2	0.1	0.1	0.1	
500	2.5	0.63	0.4	0.1	0.3	0.1	0.2	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	
300	1.5	0.38	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	
100	0.5	0.13	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	
50	0.25	0.06	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	
Performance table PHOENIX PH45 M2, Ku25x25																	
Speed n	Lifting speed		10 kN		8 kN		6 kN		4 kN		3 kN		2 kN		1 kN		
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L	
[1/min]	[m/min]		18 Nm	6 Nm	14 Nm	5 Nm	11 Nm	4 Nm	8 Nm	3 Nm	6 Nm	2 Nm	4 Nm	2 Nm	3 Nm	1 Nm	
P [kW]																	
1500	9.38	2.34	2.8	0.9	2.2	0.8	1.7	0.6	1.2	0.4	0.9	0.3	0.7	0.2	0.4	0.1	
1000	6.25	1.56	1.8	0.6	1.5	0.5	1.1	0.4	0.8	0.3	0.6	0.2	0.4	0.2	0.3	0.1	
750	4.69	1.17	1.4	0.5	1.1	0.4	0.9	0.3	0.6	0.2	0.5	0.2	0.3	0.1	0.2	0.1	
600	3.75	0.94	1.1	0.4	0.9	0.3	0.7	0.2	0.5	0.2	0.4	0.1	0.3	0.1	0.2	0.1	
500	3.13	0.78	0.9	0.3	0.7	0.3	0.6	0.2	0.4	0.1	0.3	0.1	0.2	0.1	0.1	0.1	
300	1.88	0.47	0.6	0.2	0.4	0.2	0.3	0.1	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	
100	0.63	0.16	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	
50	0.31	0.08	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	
Performance table PHOENIX PH56 M3, Ku40x40																	
Speed n	Lifting speed		25 kN		20 kN		15 kN		10 kN		5 kN		2.5 kN		1 kN		
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L	
[1/min]	[m/min]		46 Nm	17 Nm	37 Nm	13 Nm	28 Nm	10 Nm	19 Nm	7 Nm	10 Nm	4 Nm	6 Nm	2 Nm	3 Nm	1 Nm	
P [kW]																	
1500	10	2.5	7.2	2.6	5.8	2.1	4.4	1.6	3	1.1	1.6	0.6	0.9	0.3	0.4	0.2	
1000	6.67	1.67	4.8	1.7	3.9	1.4	2.9	1.1	2	0.7	1	0.4	0.6	0.2	0.3	0.1	
750	5	1.25	3.6	1.3	2.9	1	2.2	0.8	1.5	0.5	0.8	0.3	0.4	0.2	0.2	0.1	
600	4	1	2.9	1	2.3	0.8	1.8	0.6	1.2	0.4	0.6	0.2	0.3	0.1	0.2	0.1	
500	3.33	0.83	2.4	0.9	1.9	0.7	1.5	0.5	1	0.4	0.5	0.2	0.3	0.1	0.1	0.1	
300	2	0.5	1.4	0.5	1.2	0.4	0.9	0.3	0.6	0.2	0.3	0.1	0.2	0.1	0.1	0.1	
100	0.67	0.17	0.5	0.2	0.4	0.1	0.3	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	
50	0.33	0.08	0.2	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	
Performance table PHOENIX PH56 G15, Ku32x20																	
Speed n	Lifting speed		15 kN		12.5 kN		10 kN		7.5 kN		5 kN		2.5 kN		1 kN		
	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N	L	
[1/min]	[m/min]		31 Nm	20 Nm	26 Nm	17 Nm	21 Nm	14 Nm	16 Nm	11 Nm	11 Nm	7 Nm	6 Nm	4 Nm	3 Nm	2 Nm	
P [kW]																	
2250		15			5.2		4.4		3.6		2.8		2.1		1.3		0.8
1500	15	10	5	3.4	4.3	2.9	3.5	2.4	2.7	1.9	1.9	1.4	1.2	0.9	0.7	0.5	
1000	10	6.67	3.4	2.3	2.8	1.9	2.3	1.6	1.8	1.3	1.3	0.9	0.8	0.6	0.5	0.4	
750	7.5	5	2.5	1.7	2.1	1.5	1.7	1.2	1.4	0.9	1	0.7	0.6	0.4	0.4	0.3	
500	5	3.33	1.7	1.1	1.4	1	1.2	0.8	0.9	0.6	0.6	0.5	0.4	0.3	0.2	0.2	
300	3	2	1	0.7	0.9	0.6	0.7	0.5	0.5	0.4	0.4	0.3	0.2	0.2	0.1	0.1	
100	1	0.67	0.3	0.2	0.3	0.2	0.2	0.2	0.2	0.1	0.1	0.1	0.1	0.1	0.1	0.1	

Max. duty cycle at 20 °C ambient temperature: Operating mode S3 20% – 60 min. Operating mode S3 10% – 60 min. static only (dynamic not allowed)


PHOENIX

Diagrams

Performance diagram – duty cycle 10%




Performance diagram - duty cycle 20%




PHOENIX

Diagrams

PHOENIX Buckling





Critical speed (trapezoidal screw)




PHOENIX

Diagrams

PHOENIX Off-center load



Efficiency G15






PHOENIX



Technical drawings

Technical drawings

with gear type M



with gear type G



CAD & go



PHOENIX

Dimensions

Dimensions PHOENIX							
Size Dimensions [mm]	Single-stage				Multi-stage		
	PH34 M1	PH45 M2	PH56 M3	PH56 G15	PH46 M3	PH 36 M3	
A	260 + stroke + VL	300 + stroke + VL	340 + stroke + VL	369 + stroke + VL	375 + 1/2 stroke + VL	360 + 1/3 stroke + VL	
B	15	15	15	15	15	15	15
□C	138.6	160.6	182.6	182.6	182.6	182.6	182.6
□D	116.6	138.6	160.6	160.6	138.6	116.6	
E	170	195	220	249	220	199	
F	1/2 stroke	1/2 stroke	1/2 stroke	1/2 stroke	-	-	
G	300	350	400	400	-	-	
H	M32x1.5	M32x1.5	M32x1.5	M32x1.5	M32x1.5	M32x1.5	M32x1.5
I	15	22	35	-	35	45	
J	80	90	100	100	100	90	
Ø K H8	52	52	62	68	62	62	
L	60	70	83.5	122	83.5	83.5	
M	22.5	25.5	29	35	29	29	
Ø N	10 k6	14 k6	16 k6	12j6 (i=2)* 18j6 (i=3)*	16 k6	16 k6	
Ø O	75	75	90	-	90	90	
P	5	5	5	-	5	5	
□Q ±0.3	210	210	210	210	210	210	
□R	240	240	240	240	240	240	
Ø S	11	11	11	11	11	11	11

* i = Ratio




PHOENIX


Technical drawings

Technical drawings


Motor mounting flange



Gear limit switch



Inductive limit switch



CAD & go



PHOENIX

Dimensions and accessories


Dimensions PHOENIX

Size Dimensions [mm]	Single-stage			Multi-stage		
	PH34 M1	PH45 M2	PH56 M3	PH56 G15	PH46 M3	PH 36 M3
Accessories						
Motor mounting flange						
Ø T	120	140	160	160	160	140
U			Dimensions according to offer or customer request			
Gear limit switch						
V	269	277	291	329	291	291
Inductive limit switch						
W	125	145	165	194	-	-
X	22	22	22	22	-	-

Accessories

Inductive limit switch (only single-stage column)

Standard	
Supply voltage	10-30V DC*
Connection	M12
	4 pins
	Three-core
Attachment	M12x1
Output	NC
Switching current	≤ 200 mA
Length	41 mm



*AC optionally selectable, and with control from Columbus McKinnon
Engineered Products GmbH

Gear limit switch



Hand drive



- Necessary for multi-stage lifting columns
- Optional for single-stage lifting columns
- Mounting on output shaft end
- Up to 8 switching points

PHOENIX

Order code



No.	Explanation
1	Size 34 / 45 / 56 / 46 / 36
2	Gear type M1/M2/M3/G15* (*only possible with PH56)
3	Ratio N = fast / L = slow
4	Installation direction 1-6 = Alignment / A = Motor at the large profile / B = Motor at the small profile
5	Attachment plates O = Standard / X = Special
6	Stroke in mm
7	VL (extension as compared to the minimum basic build height)
8	Screw O = Standard screw or for special screw: Screw type T = Trapezoidal screw (Tr) / A = AGS screw (AGS) / K = Ball screw (Ku) Screw diameter (smallest screw for multi-stage) Screw pitch e.g. K32x20
9	Input/output shafts Gearbox type M L-R = Input left, output right R-L = Input right, output left L-O = Input left, no output R-O = Input right, no output
	<p>gear type M</p>
10	Special options/accessories Gearbox type G O = no output u = only output "u" v = only output "v" w = only output "w" uv = Outputs "u" and "v" uw = Outputs "u" and "w" vw = Outputs "v" and "w" uvw = Outputs "u", "v" and "w"
	<p>gear type G</p>

10	Special options/accessories	O = none X = Special / accessories acc. to information / drawing
Examples:		
	PH45-M2-N-2A-0-300-50-0-R-0	PH56-G15-L-1A-X-600-0-K32x20-v-0
	1-stage PH45-M3 with ratio N	1-stage PH56-G15 with ratio L
	Small profile below	Large profile below
	Standard head and foot plates	Special head and/or foot plate
	300 mm stroke, 50 mm extension	600 mm stroke, no extension
	Standard screw	Ball screw Ku32x20
	Input right, no output	Output at shaft end "v" (opposite input)